

Watkins Witness Corner S.E. Destroyed
by erosion, Wit. Corner N.W. either
under deep Fill or Destroyed by
Culvert Construction. True Corner
under 10 Foot of Road Fill.

After Searching For witness Corner
& Finding No evidence, I re-established
this corner on line from 2 Gout
corners North at double the $\frac{1}{4}$ mi.
Distances, which is on line with
stones East, and 4' North of E. East.

set C.M. 12" Below Surface, over 12" tile

N.E. Cor. Sec 34-76-19

Set: May-7-1941

Notes: Barker - Elsberry

