


Dug hole 12' square 4' deep  
 in center of Road in line with  
 Fence East & West. Found No Evidences  
 of Corner. H. Smith owner of  
 Land on West stated the stone & tile  
 was destroyed by road construction  
 For culvert constr. Established  
 Corner by chaining from N.E. & W.  
 & set C.M. over 1-2" Horse Shoe Tile

1328.0' East of  $\frac{1}{16}$  Cor. Fence  
 2656.0' " of Section Corner.  
 1323.0' West of  $\frac{1}{16}$  cor Fence  
 2646.0' " of Sec. Cor.

N.  $\frac{1}{4}$  Cor. Sec 9-77-21

Set. May-26-1941

Notes: Kennedy = Palmer & Moss



Found C.M. 4' Deep  
 12-8-55  
 Placed 1" Gas P.P.C.  
 Directly over C.M.

R.C. Vinson  
 NEW TIES Jan-16-1970

1-3-95  
 Chris Aldrich  
 G.J. SIVIK  
 ASSOCIATES