


Star: SE 1/4 27-76-18

E 1/4 ~~37~~ - 76-18

was plumbed



Set 3/4" x 30" pipe
6" deep of 60" Spk above.

Crack 228th Ave.
paving

X-nails in
Trails in

Set mid-way between
SW and SE 27-76-18
Corner falls on west
edge of west shoulder
of road.

Set June 8, 1987

By R. Mysteren
& S. Collier

Revised 30 July 1997

R. Mandysey 12/20/02

