

11/7/02 - Fnd 5"x8"x12" painted Yellow Limestone
on E. side of cor. post. at old
Fence corner.

Also fnd 6"x7"x19" Rectangular
Sandstone lying flat directly E.
of painted Limestone.

It appears to have fallen from
a position directly above the
limestone due to some erosion
at the corner.

Lowered painted Limestone 4" deep.

Set 5/8"x30" Rebar on E. side
of painted Limestone

SW Cor. NE-SE Sec. 36-76-19

