Book 2023 Page 1312 Type CORNR Pages 1 Date 4/07/2023 Time 11:43 AM

Rec Amt \$7.00


GARDEN & ASSOC.

NAOMI ELLIS, RECORDER MARION COUNTY IOWA

P.O. Box 451, Oskaloosa, Iowa 52577-0451 Phone: (641)672-2526

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

\mathbf{OF}			
Land Survey Monuments situated in Section,	Township	77	Range
, of the Fifth Principal Meridian,	MARION	County,	Iowa.
Previously recorded in <u>NO CERTIFICATE OF RECORD</u>	in County	Recorder's	Office
Monument Description and Remarks: SEE BELOW			NO SCALI



OCT. 23, 1940-MARION COUNTY ROAD DEPT: FOUND FIELD BOULDER ON NORTH SIDE OF WATKINS TILE 1-2 1/2" & 1-2" ALSO BROKEN COAL ROCK. SET C.M. 8" DEEP OVER 1-2 1/2" TILE IN PLACE AND SET FIELD BOULDER ON TOP OF C.M.

MAY 13, 1994-PLS 5594: SET 3/8" IRON PIN OVER WPA C.M.

DEC. 14, 2022—PLS 14416:
DUG 7' NORTH—SOUTH, 8' EAST—WEST, AND 6' DEEP. FOUND WPA C.M. BROKEN IN HALF. BASE WAS LAYING FLAT
5' DEEP WHILE TOP HALF WAS LAYING AT 45' ANGLE DIRECTLY NEXT TO RCP CULVERT PIPE. ALSO FOUND LARGE
FIELD BOULDER 2.5' DEEP TO NORTH OF C.M. NO TILE OR 3/8" IRON PIN FOUND. SOIL CONSISTENCY AND
SCATTERED MONUMENT EVIDENCE SHOWS CULVERT WORK LIKELY DESTROYED ORIGINAL MONUMENTATION.

JAN. 26, 2022-PLS 14416: SET 5/8" X 30" REBAR WITH YPC #14416 5" DEEP ON LINE AT PROPORTIONED DISTANCE BETWEEN NE AND SE CORNERS OF SECTION 1.

I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed Professional Land Surveyor under the laws of the State of Iowa.

Muslerer 2623 Date

Randal J. Nugteren, P.L.S. License number: 14416

My license renewal date is December 31, 2024

SEAL



List Corners to be Indexed				
Corners	Section	Township	Range	
E 1/4 COR.	1	77	19	